

Ellsworth Public Library

Building Assessment Report

November 14, 2024



ARCHITECT

Design Group Collaborative
Ellsworth, Maine

MEP ENGINEER

Richard Rollins, P.E.
Hampden, Maine

CIVIL/STRUCTURAL ENGINEER

Hedefine Engineering and Design
Ellsworth, Maine



TABLE OF CONTENTS

I. INTRODUCTION & HISTORY

II. EXECUTIVE SUMMARY

III. FIELD OBSERVATIONS

- Building Code
- Accessibility Code
- Building Shell
- Interiors
- Fire Protection
- Plumbing
- HVAC
- Electrical
- Structural
- Site/Civil

IV. APPENDIX

- Reference Plans
- Priority of Recommendations
- Cost Estimates for Recommended Work



I. INTRODUCTION & HISTORY

DRAFT



I. INTRODUCTION & HISTORY

Design Group Collaborative (DGC) was asked to provide Existing Conditions & Concept Design work to help address the Library's current and future needs. The first phase of this process is a Building Assessment Report. This report includes a review of the entire building architecture, structure, and mechanical, electrical, plumbing, fire protection and adjacent site.

Plan documentation (Addition and Renovations to Ellsworth City Library, by Bingham & Woodward, dated Jan 26, 1990) was provided by the library staff and confirmed by a walkthrough of the facility and site with library staff by DGC and the consultant firms. The library also provided DGC with an existing conditions report done by WBRC in 2013. Our report will serve as an update to that previously completed report, as well as give recommendations on current costs to upgrade the building and help the library with budgeting and fundraising.

The Ellsworth Public Library (EPL) widely considered the "crown jewel of the City," has evolved since 1897 when the original 1817 Tisdale House building was converted to a library. In the 1990's a 9,400-sf addition almost tripled the gross square footage and created accessible spaces for public gathering. Since 1990, the City of Ellsworth's population has grown from 5,975 to 8,399 in 2020, a 71% increase. The EPL has the great fortune of also continuing growth in usage and services since then. The Library has issued patron surveys, and interviewed staff to understand how the spaces could be improved to meet current and future needs.



Aerial View of the Library & Grounds

The Library's Building Committee has set the following primary goals:

- Preservation and protection of the original Tisdale building for future generations.
- Reducing energy use by increasing the building's energy performance.
- Repairs to the site features and drainage immediately surrounding the building.
- Address concerns about providing Universal Accessibility for an aging community.
- Meet the current and future needs of the library through renovation, modification, or addition to the existing building.

II. EXECUTIVE SUMMARY

DRAFT



II. EXECUTIVE SUMMARY

The Ellsworth Public Library Building Assessment Report focuses on the building and its immediate site. We reviewed the building with standard architectural analysis tools. We reviewed the shell (exterior envelope) components, structure, site, mechanical equipment, plumbing, electrical, and fire protection. This review is based on visible observations only and does not include removal of materials to verify assumptions. It does not include a hazardous material evaluation. It also does not include any concept design changes or additions.

Included within the appendix of this report is an itemized cost spreadsheet of all the recommended improvements, organized by priority based on the discussions with the Library, severity of deterioration, and impact to the Library's operations. Items listed as "Critical" should be addressed as soon as feasible. "Priority 1" items are recommended to be addressed in 1-5 years, "Priority 2" 5-10 years, "Priority 3" 10-20 years, and "Maintenance" items are recommended to be done annually as needed and the Library budget allows. A more detailed description of each Priority level can be found in the appendix.

The following Critical recommendations regarding the Library's most urgent code issues were suggested by the State Fire Marshal's Office. Even though the building is grandfathered, it is ultimately up to the Authority Having Jurisdiction (AHJ) whether the critical code issues must be addressed and what the exact timeline should be. As of this date, we have not confirmed whether the AHJ is the State or the City. If these items are performed within one year, the overall cost for the work associated with these Critical recommendations is \$270,131. If they are performed later, an escalation factor should be applied to the estimate.

Critical:

- Upgrade and extend the sprinkler system into Tisdale House
- Separate the first and lower levels of the New Addition with a 1-hour ceiling assembly
- Move the Riverside meeting room up to the first or second level, or eliminate
- Move offices to lower level, or make lower-level space a non-assembly occupancy
- Add a second means of egress at the lower level.
- Provide an accessible means of egress at the first level

The following Priority 1 recommendations have been made regarding the Library's other urgent issues to be addressed within the next 5 years. The overall cost for the work associated with these Priority 1 recommendations is \$716,232, not including escalation.

Architectural:

- Address ice damming at connector roof
- Replace New Addition windows and sills
- Replace the cupola windows and sills with historically accurate windows
- Replace tin roof at Entry



- Add storm windows to entry sidelights and transom
- Add insulation and vapor barrier at Tisdale House basement
- Replace Circulation Desk casework
- Add roof covering to north outside stairs and provide paved path to public way
- Add ADA accessible bathroom at first or second level
- Provide accessible door hardware as needed
- Add balusters to New Addition balcony railings

Mechanical, Electrical, Plumbing & Fire Protection:

- Remove the small electric water heater and tie it into adjacent hot water heating system
- Remove the indirect fired water heater and install hybrid electric heat pump
- Decouple the domestic hot water from boiler plant
- Upgrade the sewage pump station to duplex grinder pump system.
- Provide a new floor drain in Women's Room on the lower level.
- Provide a fuel oil dike around fuel oil tanks and install a leak detector system
- Provide a ceiling unit heater at the lower-level storage room
- Reinforce / brace concrete piers at large condensing unit
- Replace range hood with appropriate light duty commercial hood with fire suppression
- Provide a local bathroom exhaust fan, ductwork, and exterior wall cap
- Relocate/reroute outside air intake louver that currently is located in lower level well
- Perform Radon Test for Air for original basement area and lower-level breakroom
- Replace steam humidifier and related components on large air handler supply duct in lower level.
- Seal between telephone conduit and telephone cable to minimize water leakage
- Review/reconfigure lighting layouts and fixtures as required for renovated spaces are properly illuminated.
- Upgrade lighting at rear parking lot/entrance. Provide additional pole mounted light near entrance at top of retaining wall.
- Provide pole mounted light fixtures along two walkways from street to building entrance at original building.
- Add lighting in second floor hall of Tisdale House

Structural:

- If occupancy/use changes, investigate and reinforce Tisdale House floor framing

Civil:

- Install new exterior underdrain / French drain with drainage structures on North and East Sides of building
- Replace existing wooden guardrails with more robust vehicle guardrail system
- Relocate / remove or otherwise modify vegetation directly against the structure



III. FIELD OBSERVATIONS

DRAFT



III. FIELD OBSERVATIONS

This Existing Conditions review focuses on visible observations of the building architecture, structure, and mechanical, electrical, plumbing and fire protection systems as well as a review of the immediately adjacent site. Where necessary, the report will differentiate between the distinct generations of the building. The Tisdale House portion (originally built in 1817), the New Addition portion (built in 1991), and the Connector between the two, also built in 1991.

Building Code Review:

The Ellsworth Public Library was designed to meet the requirements of the building codes in force at the time of the construction of the 1991 Addition. Building codes have changed and improved since then, so any extensive renovation or addition will require careful review of the proposed design against the new code requirements.

During the Building Assessment process we met with the State Fire Marshal's Office (SFMO) and there were found to be two critical code-related items which exist at the Library that the SFMO requested be brought to the attention of the City of Ellsworth. The first is that the building is only partially sprinklered, which is not permitted by current building codes. The second is that the New Addition is 3 stories tall, which is not permitted by current building codes for Assembly occupancies in an unprotected wood-framed structure. The SFMO stated that these two items should be addressed before any other work on the library is undertaken.

The requirements for addressing the sprinkler system issue will be discussed in more detail in the fire protection portion of this report.

In order to address the 3-Story Assembly issue, five important measures must be taken. First, the lower level must be separated from the first-floor level by a 1-hour rated ceiling assembly. Second, the Riverside meeting room must move up to either the first or second level or be removed from the building entirely. Third, the second-floor offices must move down to the lower level or make the lower-level space a non-assembly occupancy. Fourth, a second means of egress must be added at the lower level. Finally, an accessible means of egress must be added at the first-floor level.

The reconfiguration of spaces as described above enables the building to be reclassified as a 2-story Assembly occupancy over (and completely separated from) a 1-story Business occupancy, which is allowed by code.


Note: Most of the other code-related items in the Tisdale House listed below can be permitted by the current code by virtue of the fact that it is a building listed on the Historic Register, provided a licensed professional writes a report detailing the ways in which each item meets the requirements of Chapter 43 of the NFPA 101 (Life Safety Code) with regard to Historic Buildings. So, complying with the code on any of these issues would likely not be mandatory, but rather voluntary. The lone exception being the aforementioned sprinkler system.



The Tisdale House portion of the building has a number of items which do not meet the current building code. The exterior stair risers outside the main entry door do not meet code for uniformity in height. The central stair has risers which are too tall and treads which are not deep enough. The central stair is a means of egress, but it is not enclosed. The central stair also has handrails and guardrails which are too low. Same for the guardrail at the balconies overlooking the Children's Room.



Central Stair at the Tisdale House



Balcony Rail at the Tisdale House

Note: Beyond the 3-Story Assembly issue, the code-related modifications required for the New Addition items listed below largely depend upon the level of work in the next phase of design. Minor renovations and modifications to the building would not immediately mandate that those non-code compliant items be addressed. However, extensive modifications or additions to the building would likely require the entire New Addition portion of the building to be brought up to the current building code.

The New Addition has a number of items which do not meet the current building code. The balcony and exterior egress stair guardrails do not meet code with respect to baluster spacing. The central stair is currently a means of egress, but it is not fully enclosed, nor does it lead directly to an exit. The exterior egress stairs are not protected from the elements and do not lead to a paved path. And the staff kitchen hood does not have a built-in fire suppression system. This last item will be discussed in more detail in the HVAC portion of the report.



Central Stair at the New Addition



Staff Kitchen at the New Addition

Accessibility Code Review:

As part of the 1991 Addition, the library provided ADA parking, lower-level access, lower-level ADA men’s and women’s bathrooms, and an elevator (which was upgraded in 2017) serving all three levels. However, there are still a few items which present accessibility challenges. Note: Because this building is Title II (owned by a municipality), if a renovation is undertaken, 20% of the costs of the renovation must be earmarked to address any existing accessibility issues.

The current building codes require that there be accessible egress routes in equivalent numbers to code required standard egress routes. At the Ellsworth Public Library, the code requires two means of egress off of each floor and from the building as a whole. However, the only accessible egress path from the building is at the west side of the lower level of the building. An accessible entrance must be added at the first-floor level to address this issue. This will need to be addressed as part of the critical items listed above in the building code portion of the report.



Main Entry at the Tisdale House



Sign Pointing to Lower-Level Access Point



A number of doors in the building have hardware which does not comply with ADA standards. The counter height in the staff kitchen is not ADA compliant. And some of the plumbing fixtures do not meet accessibility requirements with regards to height and clearances, including the urinals in the men's bathroom and knee space protection at the sinks. Note: Stack aisles and furniture arrangements were not reviewed for ADA compliance.




Non-Accessible Hardware at the New Addition



Exposed Sink Pipes at the New Addition

Finally, there is only one level that has accessible bathrooms and that is at the lowest level. The first and second levels are only served by one small non-accessible water closet each, located on the west side of the chimney stack. While not required by code, having an accessible bathroom on the first or second floor level, to replace (or in addition to) the small water closets would greatly increase the building's usability by the public & patrons with accessibility concerns as well as by the library's own staff.



First Water Closet at the Tisdale House



Second Water Closet at the Tisdale House

Code Recommendations:

As soon as feasible:

These items should be done before any other work at the Library is undertaken.

1. Upgrade and extend the sprinkler system into Tisdale House
2. Separate the first and lower levels of the New Addition with a 1-hour ceiling assembly
3. Move the Riverside meeting room up to the first or second level, or eliminate
4. Move the second-floor offices down to the lower level or make lower-level space a non-assembly occupancy
5. Add a second means of egress at the lower level.
6. Provide an accessible means of egress at the first level

Years 1-5:

7. Add a roof covering to north outside stairs and provide a paved path to the public way
8. Add an ADA accessible bathroom at the first or second level
9. Provide accessible door hardware as needed
10. Add balusters to the New Addition balcony railings

Years 5-10:

11. Provide an accessible counter at the staff kitchen
12. Provide knee space protection at the accessible sinks



Building Shell:

The exterior of the building is very well maintained. The asphalt shingle roof is in very good condition, having been replaced 1 to 3 years ago. However, the tin roof over the Tisdale House entry portico seems to have significantly deteriorated over the years.



Asphalt Roof at the New Addition



Tin Roof at the Tisdale House Entry

There is a single section of standing seam metal roof that was added to the east side of the connector between the two building portions. This was added in an effort to shed the snow off the roof and reduce the ice damming that has occurred there which results in leaks into the interior space below. So far, this effort has not succeeded. Ice dams and leaks are still occurring.

There are gutters and downspouts on both portions of the building. Most are in good condition, however the gutter on the north side of the New Addition is missing. This causes water and (in winter conditions) ice to collect on the two exterior egress stairs which are completely exposed to the weather.



Standing Seam Roof at the Connector



Exterior Egress Stairs Exposed to Weather

The wood clapboard siding on the building is generally in good shape. There are a few areas where the paint is starting to peel on both the wood siding and surrounding wood trim.

There is an exterior steel bulkhead located on the west side of the Connector between the New Addition and Tisdale House. The bulkhead is beginning to rust out.



Siding & Trim at the Tisdale House



Steel Bulkhead at the Connector

At the Tisdale House, the exterior walls are wood-framed construction likely with wood sheathing and tar paper beneath the clapboard siding. On the interior of the studs, the walls are finished with wood lath and plaster. There is likely no insulation in the exterior walls unless it was blown in during the intervening years since it was constructed. The roof is also wood-framed, with no insulation, but cellulose insulation of varying thickness was added at the attic level. The floor is wood-framed timbers, with additional post supports added when the building became a library. The floor joists and beams sit on a stone & brick foundation wall which is also without insulation. The basement area is primarily a dirt crawlspace with no vapor barrier.



First Floor Framing at the Tisdale House



Dirt Basement at the Tisdale House

In the attic of the Tisdale House, the cellulose insulation is penetrated in numerous places including for HVAC ductwork and the access hatch to the cupola.




Roof Framing at the Tisdale House



Attic Insulation at the Tisdale House

At the New Addition, the exterior walls are 2x6 wood studs with plywood sheathing beneath the clapboard siding. On the interior of the studs, the walls are finished with a 6-mil vapor barrier and 1/2" gypsum wall board. Typically, the exterior walls have 6" (R-19) batt insulation, except where the concrete foundation walls have been furred out with 2x4 studs. In those locations the exterior wall has 4" (R-13) batt insulation. The main roof is a wood-framed truss with 12" (R-38) batt insulation at the attic level. The Connector and low Riverside room roofs have 2x12 rafters with 10" (R-30) batt insulation. The floor is a concrete slab on grade with 2" (R-10) rigid insulation beneath a 6-mil vapor barrier. All existing insulation values, in both portions of the building, are below current code minimum requirements. See the table below.



First Floor Framing at the New Addition



Riverside Room at New Addition

At the Lower Level of the New Addition, staff have complained that the Riverside Meeting Room at the Lower Level is cold, particularly near the north wall. And the sprinkler pipes have frozen on occasion.

	Foundation	Walls	Ceiling / Roof
Existing Insulation Tisdale House	R0	R0	R20
Existing Insulation New Addition	R13	R19	R38 / R30
Current Minimally Required Insulation*	R15	R20+R5 or R13+R10	R49

*2018 International Energy Conservation Code



At the Tisdale House, with the exception of the windows in the cupola, most of the original single-pane wood exterior windows were replaced 10 years ago with dual-pane vinyl windows. At the cupola, some windows have been replaced with vinyl and some are still original single-pane wood. The cupola has had a history of leaks, and it is possible that the leaking stems from the old wood windows and their sills which do not properly shed water away from the openings. The existing entry door and sidelights are wood with single-paned glazing.



*Single-Pane Window at the Cupola
Showing a combination of old and new windows*



Single-Pane Sidelight at the Entry Door

At the New Addition, the windows are dual-pane wood clad windows. The windows are now nearly 35 years old and are beginning to show their age. The glass in some window panes has cracked, and the seals have deteriorated at others causing the panels to fog up between the two panes of glass. Library staff have reported that the large two-story windows leak in heavy rain storms. The existing exterior doors are solid wood and the sidelights and transoms at the lower-level entry have dual-paned glazing.



Fogged Glass at the New Addition



Windows & Doors at the New Addition

The two brick chimneys appear to be in good condition. Library staff said that one at the New Addition was recently redone.



Chimney & Cupola at the Tisdale House



Chimney & Penthouse at the New Addition

Note: a full and complete review of chimney flashing was not done for this report. We would recommend having a mason come and perform this task to ensure that those chimney flashings are in place and watertight.

Building Shell Recommendations:

Years 1-5:

1. Address ice damming at the Connector roof
2. Replace the New Addition windows and sills
3. Replace the remaining cupola windows and sills with historically accurate windows
4. Replace tin roof at Entry
5. Add storm windows to the entry sidelights and transom

Years 5-10:

6. Add blown-in insulation at the Tisdale House walls
7. Add blown-in insulation at the Tisdale House attic
8. Add a layer of rigid insulation at New Addition lower-level walls
9. Replace steel bulkhead cover

Years 10 – 20:

10. Replace the asphalt roof shingles at end of life

Annual Maintenance:

11. Routine maintenance of siding and trim



Interior:

The interior of the building is very well maintained. Carpet tile flooring has been installed throughout the building within the last 8 years. The plaster & gypsum board walls are in reasonably good shape, with the lone exception being an area in the Northwest corner of the first floor of the Tisdale House where some minor settlement has occurred in the past. Similarly the plaster, gypsum board and ACT ceilings are in good shape, with the exception being the second-floor plaster ceiling in the central hall of the Tisdale House, where some damage from a previous roof leak has occurred.



NW First Floor Wall at the Tisdale House



Second Floor Hall at the Tisdale House

The interior doors are primarily wood paneled, swinging doors and are either painted or stained. Most of the doors appear to be in good working order. However, a few do not have ADA compliant hardware. There has been some discoloration on the wood window sills at the two-story windows in the New Addition. Most likely caused during the previously mentioned heavy rain events. And there are some settlement cracks at the trimmed-out beams at the Children's Reading & Stack Room



Water-Stained Sill at the New Addition



Cracked Trim at the Tisdale House

The interior casework at the circulation desk is in reasonably good shape, however, it is noted by library staff that the layout does not suit their current needs, and the keyboard heights are not ergonomically correct. The staff have complained about noise reverberating from the circulation desk up into the second floor reading and stack areas. And there are no direct sight lines to either of the two primary building entries. Beyond that, there are areas of over-lighting (first floor central hall) and underlighting (Boat Room, second floor central hall & reading areas). These will be discussed in more detail in the electrical portion of the report.



Circulation Desk at the Connector




First Floor Hall Lighting at the Tisdale House

In terms of the interior environment, the condition of the basement is the most pressing concern. Water infiltration is taking place at the Southeast corner of the Tisdale House. Water runs over the dirt basement floor from one corner of the building to the opposite corner in the Northwest. Sump pumps (with drains to the exterior) and crushed stone have been added to the basement (one in each corner) to address the water once it has already entered the building. But the basement remains damp and musty. Potentially creating mold and air quality issues for the entirety of the Tisdale House wing.



Dirt Basement Floor at the Tisdale House



SE Sump Pump at the Tisdale House

Interior Recommendations:

Years 1-5:

1. Add insulation and vapor barrier at Tisdale House basement
2. Replace the Circulation Deck casework

Years 5-10:

3. Repair the ceiling at the second-floor hall
4. Repair the drywall cracks at wall and ceiling of the connector
5. Repair the plaster cracks at the NW corner of Tisdale House
6. Repair trim cracks at the Children's Room beam
7. Add sound baffles at the Circulation Deck ceiling

Years 10-20:

8. Replace the carpet tiles at end of life

Annual Maintenance:

9. Routine maintenance of walls, ceilings, and trim



Fire Protection:


1. Sprinkler Water Systems

The Sprinkler service entrance is located in the basement area of the Tisdale House. The service size is 4" cast iron piping from municipal system. A 4" service serves both 2" domestic water service and sprinkler service. The incoming water pressure is slightly higher than 100psi. This pressure is very high, but ideal for sprinkler system operation and water flows.

The sprinkler system is a partial system provided for the New Addition only. The system is assumed to be a "Life Safety System" that was allowable at time of installation. Current practice now requires the entire building to be provided with a sprinkler system designed to NFPA 13. This would require the entire building be sprinklered including the original building, concealed spaces, and attic spaces.



Sprinkler Main



Sprinkler Service

- A. Recommend upgrading and extending the sprinkler system to all areas of building to be in accordance with NFPA 13 standards. Available water pressure will be adequate for the system to operate properly without the use of an NFPA listed Fire Pump. As part of the sprinkler system upgrade a new 6" dedicated water service would be required from the municipal system into the basement for a new compliant sprinkler system riser service.

Plumbing:

1. Domestic Water Systems

The Domestic cold-water service entrance is located in the basement area of the Tisdale House. The service size is 4" cast iron piping from municipal system. A 4" service serves both 2" domestic water service and sprinkler service. Domestic Service is provided with a water meter and backflow prevention device. The incoming water pressure is slightly higher than 100psi. This pressure is excessive and creates excessive water/sewer usage and stress of fixtures and components.

In general, the remaining domestic cold water distribution system appears in good condition and adequate for current and future use.



Domestic Water Service

- A. Recommend installation of a pressure-reducing valve at the building service.

The domestic hot water is supplied by two water heaters. A small 20-gallon electric hot water heater is provided in the original basement and it serves the two Toilet Rooms located in the Tisdale House. An indirect fired water storage tank is provided in the boiler room that serves the remaining Library plumbing fixtures largely in the lower level. The indirect fired water heater is fed from boilers requiring boilers to be online during summer and shoulder seasons when boilers are not required for space heating. Water heaters appear to be in good condition but should be replaced to reduce energy consumption largely from fuel oil system.



Electric Water Heater



Existing Boiler Mate

- B. Recommend removing the electric water heater located in the original building basement and extending it to other hot water heater location in the adjacent boiler room.
- C. Recommend removing the indirect fired water heater and associated boiler hot water piping serving water heater. Provide electric hybrid heat pump water heater with 40-gallon storage capacity.

2. Sanitary Waste and Vent System

The sanitary waste serving the Tisdale House portion of the building is connected to the municipal system. The remainder of the Library is collected to a single pump sewage pump station located in the lower-level Storage Room in the New Addition. The pump station is provided with an alarm. The Pump station has failed periodically and requires service. Since this is a single pump station. When the pump fails all plumbing fixtures (except in the Tisdale House) are out of service. This has been an issue and typically happens during events occurring in the lower level.

The Women's Room on the lower level does not have a floor drain in this room in the event that a water closets gets plugged and overflows. The Men's Room on the lower level does have a floor drain.



Sewage Ejector Pump

- A. Recommend upgrading the sewage pump station to a duplex sewage pump station with grinder pumps to increase reliability. The new pump station should include a new control panel, grinder pumps and alarm floats.
 - B. Recommend installing a floor drain in the existing concrete slab at the Women's Room on the lower level. Locate floor drain near toilets and near adjacent pump station on adjacent wall. The floor would not be sloped, but the drain shall be set slightly low to allow for squeegee/mopping operations.
3. Basement Sump Pump System

Two sump pump stations with battery backup are provided in the Tisdale House basement to collect ground water/rain water that migrates thru this area from the floor and stone foundation wall. Sump pumps were recently installed, and operation has been working well.



SE Sump Pump



NW Sump Pump

4. Plumbing Fixtures

The plumbing fixtures in the toilet rooms at the Tisdale House are very limited and not adequate, or ADA compliant. The drinking fountain located on the first floor is in good condition and should remain in service. The remaining toilet rooms/Kitchenette are all located on the lower level from the main library floor. The lack of toilet facilities for ADA, elderly patrons and children on the main level should be reviewed and improved if feasible. In general, fixtures are standard water consumption fixtures and should be replaced with water savings fixtures when replacement is required.



First Floor WC



Lower-Level Sinks



Lower-Level Urinals

- A. Replace existing plumbing fixtures with water savings fixtures as fixture replacement is required.
- B. If toilet rooms are renovated, replace fixtures with water savings fixtures at that time. Refer to architectural narrative for additional toilet room consideration.

- C. Provide additional plumbing fixtures/toilet rooms as part of proposed renovation. See Code Item #8 in the architectural narrative.

HVAC:

1. Boiler Plant:

The boiler plant consists of two Weil McLain BL576 cast iron sectional boilers that appear to be in good condition. The burners are oil fired Carlin Burners that are currently running properly. The boilers can remain in service at this time, but consideration for replacement of boilers should be in the next 5 – 10 years.



Existing Boilers



Existing Oil Tanks

- A. Recommend a long-term plan to replace boilers that are reaching the end of life. Consider new boiler plant to be LP Gas fired boilers to improve energy efficiency and reduce fossil fuel consumption.

The fuel oil storage for boiler plant consists of two 330-gallon single wall fuel oil tanks located in the basement of the Tisdale House. These tanks appear to be in good condition and can remain in service at this time. Consideration should be made for replacing the tanks to dual wall tanks that would contain a fuel spill if the tank fails. This is important due to the proximity of these fuel oil tanks to the Union River at rear of the property or the introduction of this fuel oil into the sump pumps in basement.

- B. Recommend replacing fuel oil tanks with dual wall fuel oil tanks as part of boiler replacement if the owner decides fuel oil to remain as the fuel source.
- C. Recommend field building containment dike around existing oil tanks and installation of fuel oil leak detection within containment dike. Leak detectors would initiate a remote alarm upon detection of fuel leak in containment dike.
- D. Recommend removing fuel oil tanks when boilers are replaced as LP Gas fired boilers to improve energy efficiency and reduce fossil fuel consumption.

2 Hot Water Heating Distribution and Terminal Units:

The hot water distribution is largely copper and black iron piping. There are 5 inline hot water circulators located on boiler return header to distribute water from boilers to the various heating terminal units. The heating terminal units consist of a conventional hot water baseboard heat, cast iron radiators and commercial fin tube radiation at the New Addition.

The existing lower-level storage room does not have heat provided. This room is consistently cold and uncomfortable for staff working in this area.

- A. Recommend installing a ceiling mounted hot water unit heater in the lower-level storage room. Heater shall be tied to boiler plant. Provide programmable wall thermostat to cycle unit heater as required during occupied periods of library.



Cast Iron Radiator



Fin Tub Radiator

3 Air Handling/Air Conditioning System:

There are three air-handling units/air conditioning systems that serve the facility. One system serving the second-floor office area in the Tisdale House and consists of an air handler located in attic space and an exterior pad mounted 2–3-ton condensing unit. The air handler does not have an outside air connection to provide fresh air to the building occupants and is cooling only.

The second system serving the Riverside event room in the New Addition consists of an air handler located in the Mechanical Room near rear lower-level entrance and an exterior pad mounted 5-ton condensing unit located at side of the addition. The condensing unit is at the end of expected life and contains obsolete refrigeration requiring replacement in the future. The air handler does not have an outside air connection to provide fresh air to building occupants and is cooling only.

The third system serves the first and second floor Main Library areas and consists of an air handler located in basement of the Connector and an exterior pad mounted 30-ton condensing unit. The condensing unit is at the end of expected life and contains obsolete refrigeration requiring replacement in future. This condensing unit sits on concrete piers that are starting to tip. This should be monitored and reinforced to prevent further movement. This air handler has a multizone unit (2 zones) with hot deck/cold deck for zone control as well as provisions for fresh outside air for ventilation needs of Main Library.

The ductwork distribution system serving these three air handlers should be cleaned to improve indoor air quality conditions associated with ductwork distribution system. Periodic duct cleaning is recommended every 5 – 10 years and it is assumed this ductwork has not been cleaned since installation.



Attic Air Handler



Basement Air Handler



North Condensing Units



Central Condensing Unit

- A. Recommend replacing the second-floor office system with an Air/Air Heat Pump system consisting of a single outdoor unit (located at the existing location) and multiple indoor heat pump units. This system could serve as the primary heating and cooling equipment for these areas. Existing cast iron radiators in these areas would remain as backup heat source. Recommend installation of a small Energy Recovery Ventilator (ERV) to provide fresh air into these office spaces to improve indoor air quality to staff.
- B. Recommend replacing the Riverside Room system with an Air/Air Heat Pump system consisting of a single outdoor unit (located at the existing location) and a ducted indoor heat pump air handler (located at the existing location). This system could serve as the primary heating and cooling equipment for these areas. The existing perimeter radiation in these areas would remain as backup heat source. Recommend the installation of an Energy Recovery Ventilator (ERV) to provide fresh air into this event space to improve indoor air quality. If hours of use for this space are minimal, consider limited outside air intake louver to maintain fresh air requirements to space for patrons and staff.
- C. Recommend retaining an air handling unit located in basement serving the Main Library and replacing the cooling coil in unit with a heat pump coil. Replace the existing exterior condensing unit with a new Air/Air Heat Pump unit and new refrigerant piping to new heat pump coil in AHU. Provide a new Heat Pump exterior concrete pad at grade. Provide CO2 sensor in return air ductwork to modulate outside air dampers as required to maintain CO2 setpoint. Convert AHU to VAV unit and provide two VAV boxes for improved zone controls and operations.
- D. Recommend certified duct cleaning agency inspect and clean all existing ductwork and interiors of air handlers and coil sections. Duct cleaner should provide hinged access doors to allow for cleaning and future cleaning/inspections.

- E. Reinforce/brace existing large condensing unit piers to prevent further movement of concrete piers.


4 Ventilation Systems:

As noted in section 3 above, the large AHU that serves the Main Library is provided with an outside air louver to provide fresh air into this area of the building. The other two small units do not provide fresh air requirements to address Indoor Air Quality (IAQ) concerns. Recommendations for those two AHUs have been addressed in section 3 as well.

The first-floor toilet room off the Boat Room is provided with an exterior wall mounted exhaust fan that is not operable at this time. The second-floor office toilet room does not have an exhaust fan and relies on open/closing exterior windows.

The large toilet rooms located on the lower level of the New Addition are provided with a ceiling suspended heat recovery unit that exhausts air from the toilet room and provides fresh air back into toilet rooms and adjacent spaces. This unit appears in fair condition and should remain in service. The intake and exhaust air streams are currently provided in a “window well” with a plywood cover installed to keep rainwater out of well. This makes the operation of the HRV poor and ineffective.

The breakroom located on the lower level is provided with a ducted range hood without a fire suppression system. If kitchen range is not used often, consider removing range and the associated fire risk associated with ranges in public spaces. Otherwise, a new range hood with integral fire suppression is recommended.



Interior HRV



Exterior Window Well

- A. Recommend replacing range hood with new range hood that contains a fire suppression system as well as an electrical interlock to remove power from range if suppression system is activated.
- B. Recommend providing an exhaust fan and a duct to the exterior wall cap at both individual toilet rooms in the original portion of the building.
- C. Recommend relocating fresh air intake louver serving HRV to another location where fresh air can be introduced into system for proper operation.

5. Radon Mitigation System:

The Tisdale House basement consists of stone walls and concrete walls. The basement floor in this area also consists of exposed ledge, dirt floors, crushed stone, and concrete floors in poor condition. This area is susceptible to allowing Radon to migrate into the building and into the occupied spaces thru natural air movement or potentially thru the air handler located in the basement. Consideration to improve air/vapor migration from below grade into building should be addressed thru waterproofing basement floor/foundation walls. In addition to providing this waterproofing membrane system, consideration for radon testing and installation of provisions of radon mitigation and testing should be addressed. Testing in lower-level addition space should also be performed for this side of building.



Dirt Basement Floor

- A. Recommend providing radon test kits for the Tisdale House, as a minimum. Recommend testing the lower level of the New Addition in the breakroom/work area adjacent to the Riverside Room.

6. Building Temperature Controls:

The building temperature controls are provided by a mix of electrical and DDC controls. A Barber Coleman Network 8000 is provided to allow for remote access and scheduling operations. The system is obsolete at this time and should be upgraded with the next project renovation.



Existing Control Panel

- A. Recommend upgrading the existing control system to a new DDC control system based on Niagara Platform and open protocol operations.

7 Space Humidification System:

The large air handling system serving the Main Library is provided with a Honeywell Steam Humidification System in supply duct located in basement mechanical room. Existing Honeywell HM609A1000, 120V, 10A. This unit is currently not operational and needs to be replaced. Humidification is primarily needed for the Genealogy Area to protect the older publications and films. As this space is open to the Main Library, any humidification provided serves the entire area making humidification less effective. If humidification is critical for preservation, consideration should be reviewed to determine how Genealogy Area can be physically isolated from adjacent areas by partitions/doors/windows.



- A. Recommend replacing the existing Honeywell Steam Humidifier with a light commercial grade and capacity. Replacement should include new water filters and associated solenoid valves, space humidity sensor (located in the Genealogy Area on second floor).

Electrical:

1. Electrical Service:

The electrical service is underground from pole mounted transformers into a CT Cabinet located in the Tisdale House basement. The building meter from CT Cabinet is located on building exterior near library service desk. The electric service is adequate for current usage. The incoming telephone service from the street runs across the top of the CT Cabinet and water leaks from this conduit and runs onto the cabinet. Significant rusting is occurring on the cabinet and the space between the conduit and the telephone cable should be sealed to minimize water leakage and damage.



Exterior Electric Service



Interior Electric Panels

- A. Recommend sealing leak between the telephone service conduit and the telephone cable to minimize leakage and water damage. Inspect clean and paint damaged area of CT Cabinet to remove rust and prevent further deterioration.

2. Lighting:

In general, lighting has been upgraded to utilize LED bulbs and lamps. The lighting level varies from over lit in some circulation areas to marginally lit in other areas such as the stacks. The light fixtures are a combination of older style pendants in original building, newer contemporary pendants at addition, recessed downlights, wall lights and surface mounted fixtures. Lamp colors of the LED fixtures varied but in general appears to be on the warmer side of the color spectrum. The older style ceiling surface mounted

fluorescent fixtures that have been converted to LED fixtures are in poor condition and in areas contribute to the over lit spaces.

There are limited areas where light fixtures should be added and/or upgraded asap to address these areas. It would include approximately 12 – 15 ceiling mounted light fixtures consisting of surface mounted and recessed fixtures.

The stack lights have beige colored blades that tend to make these fixtures appear darker and also limited light reflecting out of these fixtures.

Exterior lighting is limited to the rear parking lot and the building entrances. There is one pole mounted light fixture that has been retrofitted with an LED lamp source. A wall mounted light is located above a lower-level entrance canopy. This wall light should have adjacent trees trimmed to improve lighting effectiveness. The lower-level canopy has two recessed downlights that are tied to a daylight sensor that is not operational. The area near the Handicapped Parking Stalls appears to be poorly lit currently. The walkways along the front/side entrance do not have any lighting along walkways. There is a large floodlight on the utility pole that shines into property. The significant trees in this area make lighting very ineffective except during winter season after leaves have fallen.

Emergency lighting and exit signage are provided throughout buildings. Exit signs and emergency light battery packs should be replaced as these unit fail.




Children's Room – Tisdale



Maine Reading Room - Addition



Stacks Area



Staff Lounge / Storage Area

- A. Recommend replacing/upgrading older style fluorescent fixtures in the original building and second floor entry near elevator with new LED fixtures. These new fixtures are dimmable and provided with a color selection range from warm white to cool white.
- B. Recommend that during proposed renovations and reconfiguration of interior, lighting levels and layouts be further reviewed with proposed changes to address areas where lighting improvements should occur.
- C. Recommend continuous review of emergency lighting and exit signage operation and replace these fixtures when defective.
- D. Recommend improving the exterior lighting at the rear parking lot. Provide one additional pole mounted light near lower-level entrance canopy. This location would improve lighting at the Handicapped parking stalls as well as pathway to building. Replace existing wall mounted photocell serving lower-level entrance canopy.
- E. Recommend providing residential scale pole mounted LED light fixtures along walkway paths from street and associated programmable timer. Assume 6 pole locations.

3. Receptacles:

In general, it appears that electrical outlets are adequate throughout the facility. The installation of tamper resistant devices should be considered in the Children's Area of the Tisdale House and in the general public spaces throughout.

A. Recommend replacing receptables in public spaces with tamper resistant devices.

4. Telephone/Internet System:

Telephone/internet service is provided in the original basement and extended to storage room at basement of addition.



Telephone Controls



IT Controls

4. Fire Alarm System:

The fire Alarm System is provided throughout the facility and appears in good condition. The fire alarm panel is Notifier NFW2-100 and is currently maintained by Norris Incorporated. Fire alarm system consists of manual pull stations, smoke detectors, heat detectors, audio/visual devices, and supervision of the sprinkler system.



Fire Alarm & Strobe



Fire Alarm Pull Station

DRAFT

5 Security and Camera System:

A security system with perimeter detection and motion detectors is provided as well as the addition of CCTV cameras at building entrances and interior spaces. The camera system can store data for a period if retrieval is required.



Fire Alarm Control Panel



Exterior Security Camera

Richard L Rollins, LLC
142 Kennebec Road
Hampden ME 04444

Structural:

The Ellsworth Public Library is a two-story structure with a full basement. The original structure (known as Tisdale House) was originally constructed in the early 1800s and consists of a two-story wood-framed structure with stone block foundation and gravel-floored basement/crawlspace. In 1991, a steel and wood-framed two-story addition was constructed to the north of the original building. The addition consists of wood and steel trussed floor and roof framing and masonry block elevator shaft, sitting on a concrete foundation (frost walls and footings) with a fully conditioned lower level.

The main structure appears to be in well-maintained condition given its age and construction. In the Tisdale House, plaster finishes and floors exhibit cracks and unevenness that is expected and normal for structures of this age and construction. The New Addition's structure also appears to be in good overall condition, with only a couple of areas that may require additional investigation.

This section does not inventory every crack or uneven floor that was observed, but rather notes areas of observable concern that may indicate underlying structural issues. This review is based on limited visible observations and does not constitute a full structural analysis of the entire building.

Foundation & First Floor Framing:

Tisdale House

In the Tisdale House, the existing foundation is predominantly grouted stone walls, brick bearing walls, and gravel floor with some areas of old brick pavers and some areas of uneven exposed ledge (photos 1, 2). Overall the stone walls appear to be sound, with no visibly discernible bulging or rotating that may indicate structural issues. Regular maintenance of grouted joints is recommended to extend the longevity of the foundation system and reduce water infiltration. The basement has had issues with water infiltration from the uphill (street) side of the site, but the installation of double sump pumps (photo 2) within the past 15 years has helped mitigate water damage from flooding (see mechanical and architectural sections for discussion of moisture control options).

The first floor is framed with wood timber joists (assumed original) supported by foundation stone walls, interior brick supports, and interior pressure-treated beams and posts that were installed in recent decades to provide additional support to the library above. The first floor houses the children and juvenile book sections and play areas. The framing overall appears to be in good condition. The first floor does exhibit unevenness that is typical of construction from this time period, but in general the framing feels solid, with little/no bouncing or deflection.



On the first-floor level of the Tisdale House, there is some historic cracking and repaired plaster observed above the windows in the Juvenile Fiction room (photo 6). This patch was reportedly made 30 years ago and has not changed since then, indicating that the condition is stable.

1991 Addition

The New Addition foundation consists of a full lower level constructed of reinforced concrete frost walls. Structural design plans indicate the presence of footings bearing on ledge, typically. Observable foundation elements all appeared to be in good condition with no structural issues (significant cracking, settling, rotating, or bulging) observed. There have been water infiltration issues in the mechanical space located in the Connector between the addition and the original building. These largely seem to be related to the location of subgrade vents located in exterior concrete “wells.” See mechanical and site sections of this report for a discussion of grading/drainage and ventilation improvements.

The first-floor framing is a combination of 2x12 floor joists and wood/steel floor trusses, supported by steel beams and posts (photos 3, 4). Floor framing is partially observable from storage and utility areas of the lower level and appears to be in good condition. There is some notable unevenness at the transition from the Tisdale House to the addition (photo 5), but that is not uncommon between construction of different types and ages and is reportedly stable, having not moved or gotten worse over the years.

Other foundation-related issues: tilting sonotube supports for HVAC equipment (photo 7) are addressed in the mechanical section of this report. Additionally, the fire escape for the second story of the addition is adequately supported by concrete foundations, however the concrete exhibits damage likely due to freeze-thaw cycles (photo 8). Eventually repairs may be needed to maintain support in these areas.

Foundation & First Floor Framing Recommendations:

1. ORIGINAL FOUNDATION – repoint grout as needed as part of regular maintenance (see photos 1, 2); coordinate with site drainage improvements (see Site section).
PRIORITY: 10-20 years
2. ADDITION FIRE ESCAPE – patching/repairs to fire escape foundations as needed to maintain adequate support and repair freeze/thaw damage (see photo 8). Coordinate with drainage improvements (see Site section).
PRIORITY: 10-20 years





Photo 1 – typical stone foundation, brick interior bearing walls, and PT interior supports



Photo 2 – grouted stone and brick foundation walls, sump pump system



Photo 3 – First floor framing in addition, from lower level



Photo 4 – First floor steel beam/post support in addition lower level



Photo 5 – First floor transition from original building to addition




Photo 6 – Plaster crack and repair on first floor, Tisdale House



Photo 7 – Tilting sonotube HVAC supports (see mechanical section)



Photo 8 – Addition fire escape foundations



Second Floor Framing:

Tisdale House

The second-floor framing was not observable due to existing finishes. It is assumed that the floor is wood framed and supported by exterior and interior bearing walls. The floors upstairs are notably uneven, which again is not uncommon for the age of the structure. The second-floor space is used for staff office and processing space (photo 5). It is very likely that the framing in this area does not meet current live load or deflection criteria, however no notable sagging or dips were observed that could indicate serious structural deficiencies. If the library ever considers converting this space to publicly accessible “reading rooms” or another use category that carries a higher live load code requirement, the framing should be investigated and reinforced as needed.

The original building also has interior balconies that are open to the children’s area below (photo 6). These spaces are not used except occasionally for light storage by the library staff.

1991 Addition

The second-floor framing was not observable due to existing finishes but is a combination of wood framing and wood/steel trusses on steel frame supports, per available plans. No deficiencies were observed.

Second Floor Framing Recommendations:

3. STAFF OFFICES and ORIGINAL BALCONIES: Investigate floor framing and load rating if use of these spaces change. (Photos 5, 6)
PRIORITY: 1-5 years (IF NEEDED)





Photo 9 - Processing office located on the second story of the Tisdale House



Photo 10 – Balcony structure as seen from the other balcony



Photo 11 – Addition second story stairs and open space



Photo 12 – Addition second story stacks



Roof Framing:

Tisdale House

The original low-sloped hipped roof structure consists of rough sawn rafters with long spans from exterior walls to the hips and ridges (photo 13). The aged wood framing is in fair condition, with areas of previous water damage from historic leaks. It is likely that the framing would not meet current code load requirements and should be analyzed and evaluated prior to any major roof renovations.

The cupola structure is in fair condition, with cracked and poor finishes and continual issues with water infiltration (see architectural section) (photo 14). The ceiling framing over the Children's Area (vaulted ceiling) has apparently decorative beams/ties running across the ceiling. The trim on these members is cracked and separated in places and should be repaired (photo 15). This does not appear to be a structural issue, coordinate with other finish repairs as described in the architectural section of this report.

1991 Addition

The roof framing was not observable for the 1991 addition, however, there appears to be issues with lateral movement ("creep") at the Connector between the Tisdale House and the New Addition, evidenced by cracking drywall and window panes (photos 16-18). According to construction plans, the framing in this area is 2x12 rafters supported by exterior walls and a Microlam ridge beam. One possible reason for the apparent movement and related damage is that the ridge beam may be slightly undersized for deflection. This roof has other issues with ice dams and water infiltration (see architectural section); these conditions may have affected the roof structure as well. When these are being addressed, the structure should be evaluated and reinforced as needed.

The main roof of the New Addition is a hipped gable roof, matching in style to the original building. According to construction drawings, this roof is wood truss construction. It was not accessible for observation at the time of the site visit. No issues were reported with the roof structure in this area.

Roof Framing Recommendations:

4. TISDALE HOUSE: In coordination with the next major renovation, evaluate and analyze roof framing and cupola for reinforcement to meet current code. (See photos 13, 14)

PRIORITY: 5-10 years



5. CONNECTOR ROOF: In coordination with roof renovations in this area, evaluate and reinforce ridge beam, ridge beam support, and related framing to reduce movement and deflection in this area. (See photos 16-18)

PRIORITY: 5-10 years (other deficiencies in this area may have higher priority)



Photo 13 – Original roof framing



Photo 14 – Interior of cupola, window access to roof



Photo 15 – Original ceiling, cracked trim



Photo 16 – Connector to addition, drywall cracks in ceiling



Photo 17 – Connector to addition, drywall cracks



Photo 18 – Connector to addition, drywall cracks, cracked window pane (lower left)

Site:

The library is situated on a 1.46-acre lot in Downtown Ellsworth. The property is bounded by The Hancock County's Sherriff's Office and Courthouse to the north, State Street to the east, Mill Road to the south, and the Union River to the west. The site contains off-street parking, retaining walls, lawn area, utilities, sidewalks, and paths. There is a significant easement for overhead electrical lines that runs across the property from the hydroelectric dam on the Union River. See the attached Report Site Plan for a graphic depiction of where the items discussed in this report are located.

Circulation:

The library is centrally located in the Downtown area. There is a small lower parking lot with capacity for 11 vehicles, including three handicap spaces (photos 1, 2), serving - the primary accessible entrance to the library, via the lower entrance and elevator. The handicap parking spaces do not appear to meet ADA guidelines. The parking lot is small and does not accommodate all traffic going to the library, so many patrons reportedly use on-street parking, or the large municipal lot located across State Street. As the site is small with grading limitations, adding additional on-site parking is likely not practical.

There are concrete sidewalks throughout the site to provide pedestrian access to the upper entrance of the library. These sidewalks serve as the primary access to the library for patrons parked off-site. Most of the concrete sidewalks have cracks and patches consistent with their age that may present trip hazards (photos 3-5). It was assumed that all asphalt and concrete sidewalks along State Street and Mill Road are owned and maintained by the City of Ellsworth and have not been included in this report.

There is also a brick and "railroad tie" timber stairs and path that lead down to the River Trail. This path is in very poor condition with aged brick and deteriorating timbers, creating trip hazards (photos 6-8).

Circulation Recommendations:

1. PARKING LOT: restripe handicap spaces to include striped loading zone per ADA (see architectural section for building accessibility considerations). (See photos 1, 2)

PRIORITY: 5-10 years



2. SIDEWALKS:

- a. Resurface/replace damaged portions of existing concrete sidewalks to remove trip hazards and provide solid walking surface from main off-site parking areas. (See photos 3-5)

PRIORITY: 5-10 years

- b. Replace lower brick and railroad tie access stairs, paths, and landings with new construction, such as gravel or paved paths with concrete or wood framed stairs or boardwalks. (See photos 6-8)

PRIORITY: 5-10 years



Photo 1 – Lower parking lot



Photo 2 – ADA parking spaces, missing loading zone



Photo 3 – Concrete sidewalks from State Street



Photo 4 – Concrete sidewalk to upper main entrance



Photo 5 – Concrete sidewalks from State Street



Photo 6 – Brick/timber path to River Trail



Photo 7 – Brick/timber path to River Trail



Photo 8 – Brick/timber path to River Trail

Drainage and Surfacing:

The site is sloping, generally running downhill from the north and State Street toward the Union River to the west/southwest. The site has been graded to create flat areas for the building, addition, and parking, with extensive use of segmental retaining walls (see Other Site Improvements for discussion of retaining walls). The upper portion of the site drains to the west and is partially collected near the main upper entrance by a drain basin and lower catch basin located near the parking lot access drive (photos 9, 10). Based on a 2013 survey, it is assumed that the lower catch basin outlet connects to a municipal stormwater line that in turn discharges to the Union River. The lower parking lot slopes to the south, where it eventually runs to the Union River.

The use of retaining walls and site grading constraints has contributed to some drainage issues, particularly at the area to the east and north of the addition and original building. Drainage problems can create numerous issues, including safety, accessibility, damage to building integrity, and potential air quality issues. Around the fire escape on the north side of the addition, the grading and location of the retaining wall between the library and the Hancock County Sherriff's Office and Courthouse reportedly sees lots of surface runoff that can create icy conditions, not conducive to an egress route (photos 11, 12)

On the uphill eastern side of the building at the connector between the original Tisdale building and the addition, there have been drainage issues related to roof runoff from three sides, and uphill grade from State Street. There are concrete wells surrounding fresh air intakes at this location that fill with surface and roof runoff. There was no observable stormwater drainage structure at this location, although an exterior sump pump has been installed in an air intake well, which is used as needed to (see mechanical section). The sump pump appears to help mitigate flooding/water infiltration but does not address the drainage problems that create the underlying issue. The outlet for the sump is piped overland around the corner of the addition and dumped on the ground surface (photos 13, 14).

The basement in the original structure (Tisdale House) contains sump pumps to help manage groundwater infiltration. The outlets to the sumps are overland and located under vegetation on the west side of the building (photo 15).

On the western side of the Connector structure between the New Addition and the Tisdale House are concrete wells surrounding fresh air intakes. Similar to the eastern side, these wells also fill with roof runoff and create a location for water infiltration into the mechanical space (photo 16). Along this area there is also a gravel drip edge under the addition's eave.

For site surfaces, most areas are either landscaped, lawns, asphalt paved parking, concrete sidewalks, or brick paved paths or landings. See the Circulation section of this report for discussion on concrete and brick paved sidewalks. Lawn and landscaped areas are generally in well maintained, good condition. Asphalt paved parking areas are over 30 years old and have exceeded their expected life span. They are exhibiting significant cracks and should be repaved (photos 17, 18). Brick pavers at the lower entrance are in good condition (photo 2).

Drainage and Surfacing Recommendations:

3. DRAINAGE IMPROVEMENTS:

- a. NORTHERN SIDE: install underdrainage with structures or French drain, to improve drainage between the addition and the northern retaining wall. Provide drainage outfall stabilized with riprap. (See photos 11, 12)

PRIORITY: 1-5 years

- b. EASTERN SIDE: install new drainage structures and underdrainage/French drain to improve drainage along the uphill eastern side of the building and connect to the location of the existing upper drain basin. Upsize existing basin as needed and connect to existing lower catch basin. Regrade the lawn area to provide positive



drainage to the new basin. Connect sump outfalls and downspouts on this side of the building to the new drainage system (coordinate with any mechanical recommendations for fresh air intake). (See photos 13, 14)

PRIORITY: 1-5 years

- c. WESTERN SIDE: coordinate with mechanical recommendations to protect fresh air intake wells from roof runoff, by either covering the wells, providing sump pumps, or relocating the vents (coordinate with mechanical section). (See photo 16)

PRIORITY: 5-10 years

- d. WESTERN SUMP OUTFALLS: improve basement sump outfalls to provide positive drainage away from the building at all locations and stabilized outfalls (e.g., splash pads). Coordinate with recommendations for vegetation modifications. (See photo 15) **PRIORITY: 5-10 years**

- 4. PAVEMENT IMPROVEMENTS: repave the lower parking area. Coordinate with Circulation recommendations for striping.

PRIORITY: 5-10 years



Photo 9 – Drain basin near upper main entrance



Photo 10 – Lower catch basin



Photo 11 – Area of poor drainage near fire escapes



Photo 12 – Area of poor drainage near fire escapes



Photo 13 – Exterior sump pump in fresh air intake well



Photo 14 – Outlet of exterior sump pump



Photo 15 – Basement sump pump outfall, typ of two



Photo 16 – Eastern well for fresh air intake, drainage issues



Photo 17 – Asphalt paved parking lot



Photo 18 – Asphalt paved parking lot

Utilities:

The library is served by town water and sewer services. No issues were reported. The building has electrical service, and there is also a significant right-of-way across the property for overhead electrical lines from the hydroelectric dam just upstream in Union River (see photos 19, 20). See Drainage and Surfacing section for discussion of onsite stormwater systems.

There is some site lighting. There is a single pole light near the entrance of the lower parking lot (photo 1), which reportedly does not provide adequate lighting, which can be a safety concern especially during darker winter months. Entrances/exits all have a building-mounted exterior light. Upper sidewalks do not appear to have any additional lighting except what is provided from street lights along State Street. A photometric study has not been performed as part of this assessment.

Utility Recommendations:

5. **SITE LIGHTING:** add additional site lighting fixtures at the lower parking lot and along the upper sidewalks. Coordinate with related recommendations. Lighting changes may require municipal review and photometrics analysis.

PRIORITY: 5-10 years

Other Site Improvements:

Due to the sloping nature of the site, a number of segmented retaining walls have been used to create level areas for parking, buildings, and lawns. These walls are over 30 years old and constructed of concrete masonry units, similar to Keystone style, with pin connections and geogrid reinforcement. The walls themselves are straight and adequately functioning to provide soil retaining, with no evidence of tilting, sliding, or bulging. The masonry units, however, are in fair to poor condition, exhibiting deterioration due to freeze-thaw cycles and age (photos 11,12, 18, 21-24). In our opinion the damaged portions of these walls are unsightly, but not in danger of imminent failure.

There is also a small dry stacked granite block retaining wall at the southern corner of the property that is in fair condition (photos 28, 29).

All segmental retaining walls have wood framed fencing along the tops. This fencing is consistently in fair to poor condition, due to age and constant weather exposure (photo 27).

The lower parking lot has asphalt curbing and a wood timber guardrail system that protects vehicles from the top of the lower/western retaining wall. This guardrail is tilting significantly, likely due to



vehicle impact (photos 24-26). It should be replaced with a more robust guardrail system. Coordinate with retaining wall improvements.

There are landscaped beds around the perimeter of the building, particularly on the eastern side of the entire library, and the western side of the original library building. In some locations the plantings are located directly adjacent to the building, which can cause damage to exterior building finishes and create visibility/safety issues (photo 30).

Other Site Improvements Recommendations

6. **RETAINING WALLS:** Segmental concrete block retaining walls are difficult to repair, as the facing blocks are integrally connected to the geogrid reinforcement. The only true fix is to replace the entire wall, which can be costly. It is recommended that the walls be replaced in a phased approach, as funding is available.
 - a. **NORTHERN RETAINING WALL:** replace with new block retaining wall or cast-in-place concrete. (See photos 11, 12)
PRIORITY: 10-20 years
 - b. **EASTERN PARKING LOT RETAINING WALL:** replace with new block retaining wall or cast-in-place concrete. (See photos 18, 21)
PRIORITY: 10-20 years
 - c. **WESTERN PARKING LOT RETAINING WALL:** replace with new block retaining wall or cast-in-place concrete. Coordinate with guardrail replacement. (See photos 24, 25)
PRIORITY: 10-20 years
 - d. **SOUTHERN GRANITE BLOCK RETAINING WALL:** reset granite block wall and regrade retained yard area. Coordinate with City sidewalk improvements, if applicable. (See photos 28, 29)
PRIORITY: 10-20 years
7. **SITE FENCING:** replace wooden fencing located on top of the northern retaining wall and the eastern parking lot retaining wall. (See photo 27)
PRIORITY: 5-10 years
8. **GUARDRAIL:** replace wooden guardrail fencing with a more robust vehicle guardrail system. Coordinate with western parking lot retaining wall replacement and asphalt paving. (See photos 24-26)
PRIORITY: 1-5 years



9. VEGETATION AGAINST STRUCTURE: Modify/relocate plantings directly adjacent to structure away from building. (See photos 30)

PRIORITY: 1-5 years



Photo 19 – Overhead hydroelectric lines



Photo 20 – Overhead hydroelectric lines



Photo 21 – Retaining, east side of parking



Photo 22 – Close up of deteriorated block caps



Photo 23 – Close up of deteriorated block facing



Photo 24 – Retaining, west side of parking lot



Photo 25 – Retaining, west side of parking lot



Photo 26 – Tilting timber guardrail



Photo 27 – Top of wall fencing, typ



Photo 28 – Granite block wall at City sidewalk



Photo 29 – Granite block wall at City sidewalk



Photo 30 – Vegetation against building

DRAFT



HEDEFINE
ENGINEERING & DESIGN, INC.



IV. APPENDIX

DRAFT





State Street

Parking Access Road

Memorial Park


Front Entrance

Library Parking

Basement Access

Parking Lot Entrance

Fire Exit





Site Plan
Ellsworth Public Library
20 State Street, Ellsworth, ME 04605



1" = 20'-0"

July 26, 2015

1







PRIORITY OF RECOMMENDATIONS

Priority Critical: As soon as feasible

Items noted in this category are related to the existing life safety concerns that should be addressed before any work listed in any other priority level can be undertaken. That means extending the sprinkler system into the Tisdale House, providing a 1-hour fire separation between the lower level and first floor of the New Addition, relocating the Riverside meeting room to an upper level, providing a second means of egress from the lower level, and providing an accessible means of egress for the first floor.

Priority 1: (1-5 years)

Items noted in this category generally speak to protecting and preserving the building by focusing on its urgent needs. Architecturally, that means addressing issues with the building's envelope by dealing with air and water infiltration and window & door replacement. As well as addressing high-priority building code and accessibility concerns. Mechanically, that means taking preventative measures to address important safety or comfort concerns. This includes providing fuel oil containment, upgrading inefficient or ineffective systems, adding critical systems where none currently exist, or replacing light fixtures and/or configurations. Structurally, that means evaluating primary supporting members prior to a change in occupancy or use. Finally, for the site, that means addressing drainage issues and safety hazards. This includes adding drainage around the building and replacing deteriorating guardrails.

Priority 2: (5-10 years)

Items noted in this category are generally less pressing, but still worth doing as time and budget allows. Things listed here improve the building's overall appearance, functionality, and efficiency. Architecturally, that means repairing interior surfaces like walls, ceilings, floors, and doors as well as adding insulation and vapor barriers where possible. As well as addressing lower priority building code and accessibility concerns. Mechanically, that means upgrading systems that are at end-of-life as well as adding systems to improve overall comfort. Replacing boilers, adding air conditioning and ventilation, and replacing plumbing fixtures. Structurally, that means monitoring known problem areas for further deterioration. Finally, for the site, that means repairing sidewalks and walkways, repaving the parking, and replacing fences and site lighting.

Priority 3: (10-20 years)

Items noted in this category are focused on forward thinking. What might the building, its patrons, or staff need as the years go on? Architecturally, that means replacing the roofing & siding at their end-of-life, and possibly repairing some items that did not get addressed in Priority 2. Structurally, that means maintaining, or replacing areas, of deterioration. And for the site, that means making repairs to the granite & CMU retaining walls.



ELLSWORTH PUBLIC LIBRARY - BUILDING ASSESSMENT REPORT

Recommended Renovations, Repairs & Upgrades



SUMMARY OF BUILDING RECOMMENDATIONS by PRIORITY

Date: 11/14/24

PRIORITY	SCOPE	REPORT ITEM	LOCATION	DESCRIPTION*	QUANTITY**	OPINION OF PROBABLE COST***	ESTIMATOR NOTES
Critical	Code	1	Throughout Tisdale House	Upgrade and extend sprinkler system throughout entire building in accordance to NFPA 13 Standards Including a new 6" dedicated water service	4500 sf building	\$ 163,779.00	Includes tying into water line on State Street; Fire Pump is excluded and assumed not required.
Critical	Code	2	Lower Level of New Addition	Separate the first and lower levels of the New Addition with a 1-hour ceiling assembly	3200 sf of strapping and 5/8" GWB	\$ 49,632.00	
Critical	Code	3	Lower Level of New Addition	Move the Riverside meeting room up to the first or second level, or eliminate		Assume No Cost	
Critical	Code	4	Lower Level of New Addition	Move the second-floor offices down to the lower level or make lower-level space a non-assembly occupancy		Assume No Cost	
Critical	Code	5	Lower Level of New Addition	Add a second means of egress at the lower level.	Add exterior door and 25lf of 4' conc. walkway with railing	\$ 19,813.20	
Critical	Code	6	Tisdale House South Side	Provide ADA compliant access to main entry at Tisdale House	24' ramp and railing	\$ 36,907.20	Cost could be less if ramp is a temporary one
				Priority Critical (1 year)	Subtotal	\$ 270,131.40	

PRIORITY	SCOPE	REPORT ITEM	LOCATION	DESCRIPTION*	QUANTITY**	OPINION OF PROBABLE COST***	ESTIMATOR NOTES
1	Shell	1	Connector Roof East Side	Address ice damming at connector roof. Re-roof & reflash with waterproof membrane	200 sf.	\$ 14,520.00	
1	Shell	2	Throughout New Addition	Replace New Addition windows and sills	(28) 3'x5' windows & (2) 9'x15' windows	\$ 75,952.80	
1	Shell	3	Tisdale House Cupola	Replace cupola windows and sills with historically accurate windows	(6) 2'x4' windows	\$ 11,088.00	
1	Shell	4	Tisdale House Entry Roof	Replace tin roof at Entry	60 sf.	\$ 6,520.80	
1	Shell	5	Tisdale House Entry Foyer	Add storm windows to entry sidelights and transom	50 sf.	\$ 2,310.00	
1	Interior	1	Tisdale House Basement	Add sprayfoam insulation at walls and vapor barrier at floor at Tisdale House basement	1600 sf floor VB & 1000 sf wall SF	\$ 33,462.00	
1	Interior	2	Connector 1st Floor	Replace Circulation Desk casework	40 lf.	\$ 65,736.00	Director Priority
1	Code	7	New Addition North Side	Add roof covering to north outside stairs and provide paved path to public way	5' x 25' roof and 140lf of 4' wide concrete paved path	\$ 33,930.60	
1	Code	8	1st or 2nd Floor	Add ADA accessible bathroom at first or second level	8' x 10' bathroom	\$ 45,672.00	Assume renovate space for new bathroom
1	Code	9	Throughout Building	Provide accessible door hardware as needed	10 doors	\$ 18,216.00	
1	Code	10	New Addition 2nd Floor	Add balusters to New Addition balcony railings	150 lf.	\$ 44,550.00	Director Priority
1	Plumbing	1.B	BASEMENT	Remove small electric water heater and tie into adjacent hot water heating system.		\$ 4,593.60	
1	Plumbing	1.C	BASEMENT	Remove indirect fired water heater and install hybrid electric heat pump. Decouple domestic hot water from boiler plant to allow boiler off during summer and shoulder seasons.		\$ 20,407.20	
1	Plumbing	2.A	BASEMENT	Upgrade sewage pump station and pumps from single pump system to duplex grinder pump system.		\$ 59,400.00	
1	Plumbing	2.B	BASEMENT	Provide new floor drain (with trap primer) in Women's Room on lower level. Cut and patch concrete floor and finishes as required.		\$ 16,473.60	
1	HVAC	1.C	BASEMENT	Provide fuel oil dike around fuel oil tanks and install leak detector system. Seal all cracks in slab within containment areas.	100 sf.	\$ 3,300.00	

1	HVAC	2.A	BASEMENT STORAGE ROOM	Provide ceiling unit heater at basement storage room and tie into hot water boiler piping in area.		\$	5,940.00	
1	HVAC	3.E	Exterior	Reinforce/brace concrete piers at large condensing unit. Provide angle iron supports/cross bracing at piers.		\$	7,920.00	
1	HVAC	4.A	Basement Breakroom	Replace range hood with appropriate light duty commercial hood with fire suppression system install.		\$	14,282.40	
1	HVAC	4.B	Original Building Toilet Rooms	Provide local bathroom exhaust fan, ductwork and exterior wall cap. Fan to be quiet operation and to be tied to light fixture for operation.		\$	3,471.60	
1	HVAC	4.C	BASEMENT/TOILET ROOMS	Relocate/reroute outside air intake louver that currently is located adjacent to exhaust louver in a window well that is covered over with plywood. New intake louver shall be 10 minimum away from exhaust air discharge.		\$	3,458.40	
1	HVAC	5.A	BASEMENT	Perform Radon Test for Air for original basement area and lower level breakroom. Test results to be sent to independent lab such as Northeast Laboratories in Maine.		\$	1,980.00	
1	HVAC	7.A	BASEMENT	Replace steam humidifier and related components on large air handler supply duct in basement. Humidifier is intended to provide humidification to Genealogy Area on Second Floor.		\$	39,256.80	Does not include closing off Genealogy from the rest of the building.
1	Electrical	1.A	BASEMENT/ELECTRIC SERVICE	Seal between telephone conduit and telephone cable to minimize water leakage. Clean interior and exterior of CT cabinet and prime/paint damage areas repaired.		\$	2,560.80	
1	Electrical	2.B	THROUGHOUT BUILDING	Review/reconfigure lighting layouts and fixtures as required for renovated spaces are properly illuminated.	Assume 50 new light fixtures	\$	30,855.00	Director Priority
1	Electrical	2.D	EXTERIOR PARKING LOT	Upgrade lighting at rear parking lot/entrance. Provide additional pole mounted light near entrance at top of retaining wall. Assume 16' pole with LED fixture with full cutoff and photocell control. Replace existing wall mounted photocell that		\$	19,074.00	
1	Electrical	2.E	EXTERIOR WALKWAYS	Provide pole mounted light fixtures along two walkways from street to building entrance at original building. Assume 6 fixtures, 16' poles with ornamental period light fixtures. Tie into existing exterior lighting time clock in basement.		\$	56,364.00	
1	Structural	3	STAFF OFFICES/PROCESSING; ORIGINAL BALCONIES	if occupancy/use changes, investigate and reinforce floor framing as needed to meet code	approximately 700 sf	\$	23,100.00	
1	Site	3.a	NORTHERN SIDE DRAINAGE	Install new underdrain/French drain with structure; stabilized riprap outfall; connect downspouts to new drainage	75 lf	\$	13,068.00	
1	Site	3.b	EASTERN SIDE DRAINAGE	Install new underdrain/French drain with structure; regrade lawn area to drain to new basin; connect and upgrade existing upper drain basin and piping to connect to lower catch basin; connect eastern exterior sump outfall and downspouts to new	110 lf	\$	22,539.00	
1	Site	8	GUARDRAILS	Replace existing wooden guardrails with more robust vehicle guardrail system. Coordinate with western parking lot retaining wall replacement (5.c) and asphalt paving (4)	approx. 160 lf	\$	13,167.00	
1	Site	9	BUILDING PERIMETER	Relocate/remove or otherwise modify vegetation directly against the structure to be not touching the building to improve visibility and prevent deterioration.	1 ls	\$	3,062.40	
				Priority 1 (1-5 years)	Subtotal	\$	716,232.00	

PRIORITY	SCOPE	REPORT ITEM	LOCATION	DESCRIPTION*	QUANTITY**	OPINION OF PROBABLE COST***	ESTIMATOR NOTES
2	Shell	6	Throughout Tisdale House	Add blown-in insulation at Tisdale House walls	2500 sf.	\$ 22,743.60	Includes cutting & patching of walls as needed
2	Shell	7	Tisdale House Attic	Add blown-in insulation at Tisdale House attic	1600 sf.	\$ 11,616.00	
2	Shell	8	New Addition Basement	Add layer of rigid insulation at New Addition basement walls	1200 sf.	\$ 5,544.00	
2	Shell	9	Connector West Side	Replace steel bulkhead cover	1 unit	\$ 2,732.40	
2	Interior	3	Tisdale House 2nd Floor	Repair ceiling at second floor hall	250 sf.	\$ 4,950.00	
2	Interior	4	Connector 2nd Floor	Repair drywall cracks at wall and ceiling of connector	50 sf.	\$ 1,650.00	
2	Interior	5	Tisdale House 1st Floor	Repair plaster cracks an NW corner of Tisdale House	25 sf.	\$ 1,815.00	
2	Interior	6	Tisdale House 2nd Floor	Repair trim cracks and Children's Room beam	10 lf	\$ 2,296.80	
2	Interior	7	Connector 2nd Floor	Add sound baffles at Circulation Deck ceiling	200 sf	\$ 17,160.00	
2	Code	11	New Addition Basement	Provide accessible counter at staff kitchen	4 lf. New counter and cabinets	\$ 3,564.00	Base cabinets and counter only
2	Code	12	New Addition Basement	Provide knee space protection at accessible sinks	4 sinks	\$ 2,376.00	
2	Plumbing	1.A	BASEMENT	Install pressure reducing valve at domestic water service. Set at 60psf from current 100+ psi.		\$ 1,491.60	

2	Plumbing	4.A	TOILET ROOMS	Replace existing plumbing fixtures with water savings plumbing fixtures.	14 fixtures	\$	60,060.00	
2	HVAC	1.A	BASEMENT	Replace boiler plant with new boiler(s) and components		\$	47,916.00	Includes recirc pump
2	HVAC	1.B	BASEMENT	If retaining fuel oil for boilers use, replace single wall fuel oil tanks with dual wall indoor fuel oil tanks,	2 tanks	\$	16,473.60	
2	HVAC	1.D	BASEMENT	If new boilers are LPG fired, remove all fuel oil tanks and associated piping. New LPG stand(s) shall be located at rear of site. Tanks can be exposed or buried to minimize visual impact.		\$	27,878.40	
2	HVAC	3.A	ATTIC/SECOND FLOOR OFFICES	Replace 3 ton split system air conditioning system and install new Air/Air Heat Pump outdoor unit with remote wall mounted indoor units. Provide small Energy Recovery Ventilator to provide fresh air to the Second Floor Offices.		\$	42,187.20	
2	HVAC	3.B	LOWER LEVEL EVENT SPACE	Replace 30 ton split system air conditioning system and install new Air/Air Heat Pump outdoor unit with remote ducted indoor unit in Mechanical space. Provide Energy Recovery Ventilator to provide fresh air to the Event Space if hours of		\$	144,091.20	
2	HVAC	3.C	BASEMENT/MAIN LIBRARY	Replace 5 ton split system HVAC air handing system and install new Air/Air Heat Pump outdoor unit with remote ducted indoor unit in Mechanical space. Provide 2 VAV boxes with reheat coils to maintain current 2 zones of the multizone air		\$	43,507.20	
2	HVAC	6.A	BASEMENT/BOILER ROOM	Upgrade existing temperature controls system as part of major upgrades to equipment recommended above.		\$	33,000.00	
2	Electrical	3.A	PUBLIC SPACES	Provide tamper resistant receptacles in all public areas.		\$	23,100.00	Assume 100 ea
2	Structural	4	TISDALE HOUSE	Analyze existing roof for reinforcement to meet current code	1760 sf	\$	59,280.00	Investigation and repair costs
2	Structural	5	CONNECTOR ROOF	Analyze existing roof framing to address apparent deflection issues, reinforce as needed	440 sf	\$	21,780.00	Investigation and repair costs
2	Site	2.a	UPPER SIDEWALKS	Patch/replace damaged sections of pedestrian concrete sidewalks	approx. 350 sf concrete sidewalk (assumed ~25% of existing)	\$	8,085.00	
2	Site	2.b	LOWER PATH TO RIVER TRAIL	Reconstruct stair and path access to River Trail	approx. 85 lf of path/patio, 4' average width	\$	27,654.00	
2	Site	3.c	WESTERN SIDE DRAINAGE	Coordinate with mechanical recommendation to protect fresh air intakes from water infiltration at concrete wells.	1 ls		Assume No Cost	
2	Site	3.d	WESTERN SUMP OUTFALLS	Improve sump outlets with positive drainage away from building and new stabilized outlets (e.g. splash pads)	2 ea	\$	4,488.00	
2	Site	4	PARKING LOT	Repave existing parking lot. Coordinate with ADA striping and retaining wall recommendations.	approx. 5700 sf	\$	63,954.00	
2	Site	1	PARKING LOT	Restripe handicapped parking spaces to include striped loading zone meeting ADA	1 ls	\$	6,600.00	
2	Site	7	SITE FENCING	Replace wooden fencing along tops of the northern retaining wall and eastern parking lot retaining wall	approx. 60 lf northern wall approx. 110 lf eastern parking lot wall	\$	41,962.80	
				Priority 2 (5-10 years)	Subtotal	\$	749,956.80	

PRIORITY	SCOPE	REPORT ITEM	LOCATION	DESCRIPTION*	QUANTITY**	OPINION OF PROBABLE COST***	ESTIMATOR NOTES
3	Shell	10	Throughout Building	Replace asphalt roof shingles at end of life	6000 sf	\$	95,040.00
3	Interior	8	Throughout Building	Replace carpet tiles at end of life	9000 sf.	\$	103,950.00
3	Structural	1	ORIGINAL FOUNDATION	repoint grout/mortar at stone foundation as needed for general maintenance	+/- 160 lf of stone wall, average height: 6'	\$	57,024.00
3	Structural	2	ADDITION FIRE ESCAPE	repair/patch fire escape stair foundation to maintain adequate support for stair structure	1 ls	\$	3,062.40
3	Site	6.a	NORTHERN RETAINING WALL	Replace deteriorating wall with new segmented retaining wall or cast-in-place concrete retaining wall; coordinate with fencing replacement	approx. 60 lf, max height: 8'	\$	74,052.00
3	Site	6.b	EASTERN PARKING LOT RETAINING WALL	Replace deteriorating wall with new segmented retaining wall or cast-in-place concrete retaining wall; coordinate with fencing replacement	approx. 110 lf, max height: 6'	\$	113,982.00
3	Site	6.c	WESTERN PARKING LOT RETAINING WALL	Replace deteriorating wall with new segmented retaining wall or cast-in-place concrete retaining wall; coordinate with guardrail replacement	approx. 175 lf, max height: 9'	\$	244,860.00
3	Site	6.d	GRANITE BLOCK RETAINING WALL	Reset granite block wall, regrade retained yard area	approx. 40 lf, max height: 3'	\$	17,226.00
				Priority 3 (10-20 years)	Subtotal	\$	709,196.40

PRIORITY	SCOPE	REPORT	LOCATION	DESCRIPTION*	QUANTITY**	OPINION OF PROBABLE COST***	ESTIMATOR NOTES
4	Shell	11	Throughout Building	Routine maintenance of siding and trim			
4	Interior	9	Throughout Building	Routine maintenance of walls, ceilings, and trim			
4	HVAC	3.D	Throughout building	Maintain/Clean existing HVAC ductwork, equipment and terminal units on all three systems.			
4	Electrical	2.C	Throughout building	Maintain/replace existing emergency lighting battery packs and exit signage as batteries fail Routine test fixtures on a bi-annual basis.			

*See report narrative for additional information and photos.

**Quantities are approximate and for estimating, planning & budget purposes only.

***Pricing includes General Conditions @ 10%, Contingency @ 15%, Contractor Fee @ 5%, Bond & Insurances @ 2% (32% total). Escalation is excluded, see below.

PRIORITIES:	TIMEFRAME:	Escalation Rate of 3% per year:	NOTES:	SUBTOTAL:	ESCALATION:	GRAND TOTAL:
Critical	COMPLETE IN 1 YEAR	0%		\$270,131.40	\$0.00	\$270,131.40
1	COMPLETE IN 1-5 YEARS	12% avg over 5 year span		\$716,232.00	\$85,947.84	\$802,179.84
2	COMPLETE IN 5-10 YEARS	30% avg over 10 year span		\$749,956.80	\$224,987.04	\$974,943.84
3	COMPLETE IN 10-20 YEARS	60% avg over 10 year span		\$709,196.40	\$425,517.84	\$1,134,714.24
				\$2,445,516.60	\$736,452.72	\$3,181,969.32

Note: The opinion of probable costs given are conceptual estimates that provide a rough order of magnitude. These probable costs could be 10% above or below the stated value. See high & low range outlined below.

PRIORITIES:	TIMEFRAME:	HIGH:	LOW:	AVERAGE:
Critical	COMPLETE IN 1 YEAR	\$297,144.54	\$243,118.26	\$270,131.40
1	COMPLETE IN 1-5 YEARS	\$787,855.20	\$644,608.80	\$716,232.00
2	COMPLETE IN 5-10 YEARS	\$824,952.48	\$674,961.12	\$749,956.80
3	COMPLETE IN 10-20 YEARS	\$780,116.04	\$638,276.76	\$709,196.40